



Figure 8-7. Time-series of water clarity (top panel, red line is low-pass-filtered) and estimated bed shear stress (bottom panel). The transmissometer was fouled after early August. The vertical bands in the bottom panel designate the beach contamination events. Shear stress values within or above the horizontal band are able to resuspend very fine sands and silts.